

PROGRESS UPDATE
MAY 2012





Tower C from East side.



Tower C view from South East Corner.



Both Tower C and D from South side.



Both Tower C and D from North west Corner.



Both

Tower C and D from North side.



Road Formation Works



Club House First floor slab shuttering in progress



Fixing of Window, Utility grills and Aluminium windows are in progress



Fixing of Internal door shutters in progress.



Internal Painting(Primary putty works are in Progress).



Internal wiring works are in progress